


BOHRPRESSE 16mm 2604



www.ronixtools.com






SPEZIFIKATIONEN

Modell	2604
Voltzahl	220-240V
Motorleistung	550W
Bohrfutterkapazität	3~16mm
Bohrkapazität	Stahl: 13mm Holz: 20mm Kunststoff: 16mm
Spindelhub	80mm
Geschwindigkeitsklasse	16
Geschwindigkeit	180~2770U/min
Spindelkegel	MT2
Abstand von der Spindelachse zur Säule	162.5mm
Abstand vom Spindelende zur Tischoberfläche	450mm
Abstand vom Spindelende zur Basisoberfläche	630mm
Schwung	325mm
Tischgröße	250x250mm
Basisgröße	420x250mm
Säulendurchmesser	72mm
Höhe	980mm
Nettogewicht/Bruttogewicht	39/42Kg



Zubehör:	
Federscheibe 10	4
Außensechskantschraube M10x25	4
Klemmschiene	1
Sechskantstangenschlüssel 4	1
Sechskantstangenschlüssel 3	1
Griff & Spitze	3
Dickes Bremseisen	1
Bohrfutterschutz	1
Bohrfutter & Kegel	1
Spindel	1
Cross Recess Pan Hd Screw M5	1
Flache Unterlegscheibe M5	1
Bolzen M12x40	4
Schraubstock 4"+D63	1
4" Flache Unterlegscheibe 12	4
Federscheibe 12	4

WERKZEUGTEILE





SPEZIFIKATIONEN



MARNUNG!

Um elektrische Gefahren, Brandgefahren oder Beschädigungen des Werkzeugs zu vermeiden, verwenden Sie den richtigen Schutzschalter. Verwenden Sie für Ihre Werkzeuge einen separaten Stromkreis. Um einen Schock oder Brand zu vermeiden, ersetzen Sie das Netzkabel sofort, wenn es abgenutzt, geschnitten oder in irgendeiner Weise beschädigt ist.



WARNUNG!

Um Fehler zu vermeiden, die zu schweren Verletzungen führen könnten. schließen Sie die Bohrmaschine nicht an, bevor Sie das Folgende gelesen und verstanden haben:

- 1-LESEN Sie und machen Sie sich mit der gesamten Bedienungsanleitung vertraut. LERNEN Sie die Anwendung des Werkzeugs, seine Grenzen und möglichen Gefahren kennen.
- 2- HALTEN SIE SCHUTZVORRICHTUNGEN AN ORT UND STELLE und in funktionstüchtigem Zustand.
- 3- ENTFERNEN SIE EINSTELLSCHLÜSSEL UND SCHRAUBENSCHLÜSSEL. Gewöhnen Sie sich daran, zu überprüfen. dass Schlüssel und Einstellschraubenschlüssel vor dem Einschalten vom Werkzeug entfernt sind.
- 4- HALTEN SIE DEN ARBEITSBEREICH SAUBER, Unordentliche Bereiche und Bänke laden zu Unfällen ein.
- 5- VERWENDEN SIE DAS WERKZEUG NICHT IN GEFÄHRLICHER UMGEBUNG. Verwenden Sie Elektrowerkzeuge nicht in feuchten oder nassen Umgebungen oder setzen Sie sie nicht Regen aus. Halten Sie den Arbeitsbereich aut beleuchtet.
- 6- HALTEN SIE KINDER FERN. Alle Besucher sollten in sicherer Entfernung vom Arbeitsbereich gehalten werden.
- 7- MACHEN SIE DIE WERKSTATT KINDERSICHER mit Vorhängeschlössern.
- 8- ZWINGEN SIE DAS WERKZEUG NICHT. Es wird die Arbeit besser



und sicherer in dem Tempo erledigen, für das es konzipiert wurde.

- 9- VERWENDEN SIE DAS RICHTIGE WERKZEUG. Zwingen Sie das Werkzeug oder den Aufsatz nicht dazu, eine Arbeit zu verrichten, für die es nicht konzipiert wurde.
- 10- VERWENDEN SIE DAS RICHTIGE VERLÄNGERUNGSKABEL. Stellen Sie sicher, dass Ihr Verlängerungskabel in gutem Zustand ist. Wenn Sie ein Verlängerungskabel verwenden, stellen Sie sicher, dass es stark genug ist, um den Strom zu tragen, den Ihr Produkt ziehen wird. Ein zu dünnes Kabel führt zu einem Spannungsabfall und zu einem Leistungsverlust, der dazu führen kann, dass das Werkzeug überhitzt.
- 11- TRAGEN SIE DIE RICHTIGE KLEIDUNG. Tragen Sie keine lockere Kleidung, Handschuhe, Krawatten, Ringe, Armbänder oder anderen Schmuck, der in beweglichen Teilen hängen bleiben könnte. Rutschfeste Schuhe werden empfohlen. Tragen Sie einen Schutz für das Haar, um langes Haar zu bändigen.
- 12- TRAGEN SIE IMMER AUGENSCHUTZ. Jede Bohrmaschine kann Fremdkörper in die Augen schleudern, die zu dauerhaften Augenschäden führen könnten. Tragen Sie immer Schutzbrillen (keine Brillen). Normale Brillen haben nur stoßfeste Linsen. Sie sind KEINE Schutzbrillen.
- 13- SICHERN SIE DIE ARBEIT. Verwenden Sie Klemmen oder einen Schraubstock, um die Arbeit zu halten, wenn es praktisch ist. Es ist sicherer, als Ihre Hand zu verwenden, und es befreit beide Hände, um das Werkzeug zu bedienen.
- 14- TRENNEN SIE WERKZEUGE vor der Wartung; beim Wechseln von Zubehör wie Klingen, Bits, Fräsern und dergleichen.
- 15- REDUZIEREN SIE DAS RISIKO EINES UNBEABSICHTIGTEN STARTENS. Stellen Sie sicher, dass der Schalter vor dem Einstecken in der AUS-Position ist.
- 16- VERWENDEN SIE EMPFOHLENES ZUBEHÖR. Konsultieren Sie die Bedienungsanleitung für empfohlenes Zubehör. Die Verwendung von ungeeignetem Zubehör kann zu schweren Verletzungen führen.
- 17- STEHEN SIE NIEMALS AUF DEM WERKZEUG. Es könnte zu schweren Verletzungen kommen, wenn das Werkzeug kippt oder das



Schneidwerkzeug unbeabsichtigt berührt wird.

18- ÜBERPRÜFEN SIE AUF BESCHÄDIGTE TEILE. Vor der weiteren Verwendung des Werkzeugs sollte ein beschädigter Schutz oder ein anderes Teil sorgfältig überprüft werden, um festzustellen, ob es ordnungsgemäß funktioniert und seine beabsichtigte Funktion erfüllt überprüfen Sie die Ausrichtung beweglicher Teile, die Bindung beweglicher Teile, den Bruch von Teilen, die Montage und alle anderen Bedingungen, die den Betrieb beeinflussen könnten. Ein beschädigter Schutz oder ein anderes Teil sollte ordnungsgemäß repariert oder ersetzt werden.

19- LASSEN SIE DAS WERKZEUG NIEMALS UNBEAUFSICHTIGT LAUFEN. SCHALTEN SIE DIE STROMVERSORGUNG AUF "AUS". Verlassen Sie das Werkzeug nicht, bis es vollständig angehalten hat. 20- ÜBERDEHNEN SIE SICH NICHT. Behalten Sie jederzeit einen

ordentlichen Stand und Gleichgewicht.

21-PFLEGEN SIE WERKZEUGE MIT SORGFALT. Halten Sie Werkzeuge scharf und sauber für die beste und sicherste Leistung. Befolgen Sie die Anweisungen zum Schmieren und Wechseln von Zubehör.

22- Verwenden Sie keine Elektrowerkzeuge in Gegenwart von brennbaren Flüssigkeiten oder Gasen.

23- BETREIBEN SIE das Werkzeug nicht, wenn Sie unter dem Einfluss von Drogen, Alkohol oder Medikamenten stehen, die Ihre Fähigkeit beeinträchtigen könnten, das Werkzeug ordnungsgemäß zu verwenden. 24- BETREIBEN SIE die Bohrmaschine immer in einem gut belüfteten Bereich und sorgen Sie für eine ordnungsgemäße Staubentfernung. Verwenden Sie wann immer möglich Staubabsaugsysteme. Von bestimmten Materialien erzeugter Staub kann gesundheitsschädlich sein.

SPEZIFISCHE SICHERHEITSANWEISUNGEN



WARNUNG!

Zu Ihrer eigenen Sicherheit versuchen Sie nicht, Ihre Bohrmaschine zu verwenden oder anzuschließen, bevor sie vollständig gemäß den Anweisungen montiert und installiert ist und bevor Sie diese



Bedienungsanleitung gelesen und verstanden haben.

- 1- DIESE BOHRMASCHINE ist nur für die Verwendung in trockenen Bedingungen und nur für den Innenbereich vorgesehen.
- 2- TRAGEN SIE AUGENSCHUTZ, VERWENDEN Sie eine Gesichts oder Staubschutzmaske zusammen mit Schutzbrillen, wenn die Bohrarbeit staubig ist. VERWENDEN Sie Gehörschutz, insbesondere bei längerer Benutzung.
- 3- TRAGEN SIE KEINE Handschuhe, Krawatten oder lockere Kleidung.
- 4- VERSUCHEN SIE NICHT, Material zu bohren, das zu klein ist, um sicher gehalten zu werden.
- 5- HALTEN SIE IMMER die Hände aus dem Weg des Bohrers. Vermeiden Sie ungeschickte Handpositionen, bei denen ein plötzliches Abrutschen dazu führen könnte, dass Ihre Hand in den Bohrer gerät.
- 6- INSTALLIEREN ODER VERWENDEN SIE KEINEN Bohrer, der länger als 175 mm ist oder mehr als 150 mm unterhalb der Bohrfutterbacken. herausragt. Sie können plötzlich nach außen biegen oder brechen.
- 7- VERWENDEN SIE KEINE Drahtbürsten, Fräser, Profilfräser, Kreis (flug) schneider oder Rotationshobel auf dieser Bohrmaschine.
- 8- WENN Sie ein großes Materialstück schneiden, stellen Sie sicher, dass es vollständig auf Tischhöhe unterstützt wird.
- 9- FÜHREN SIE KEINE Operation freihändig durch. HALTEN SIE das Werkstück immer fest gegen den Tisch, damit es nicht wackelt oder sich verdreht. Verwenden Sie Klemmen oder einen Schraubstock für instabile Werkstücke.
- 10- STELLEN SIE SICHER, dass keine Nägel oder Fremdkörper im Teil des Werkstücks vorhanden sind, das gebohrt werden soll.
- 11- KLEMMEN SIE DAS WERKSTÜCK ODER STÜTZEN SIE ES gegen die linke Seite der Säule, um eine Drehung zu verhindern. Wenn es zu kurz ist oder der Tisch geneigt ist, klemmen Sie es fest an den Tisch.
- 12- WENN DAS WERKSTÜCK so über den Tisch hinausragt, dass es fallen oder kippen würde, wenn es nicht gehalten wird, klemmen Sie es an den Tisch oder sorgen Sie für zusätzliche Unterstützung.
- 13- SICHERN SIE DIE ARBEIT. Verwenden Sie Klemmen oder einen



Schraubstock, um die Arbeit zu halten, wenn es praktisch ist. Es ist sicherer, als Ihre Hand zu verwenden, und es befreit beide Hände, um das Werkzeug zu bedienen.

- 14- STELLEN SIE SICHER, dass alle Klemmen und Verriegelungen vor dem Bohren fest angezogen sind.
- 15- VERANKERN SIE DEN KOPF und die Tischstütze sicher an der Säule und den Tisch an der Tischstütze, bevor Sie die Bohrmaschine in Betrieb nehmen.
- 16- SCHALTEN SIE Ihre Bohrmaschine NIEMALS ein, bevor Sie den Tisch von allen Gegenständen (Werkzeuge, Holzreste usw.) geräumt haben.
- 17- VOR DEM STARTEN der Operation, betätigen Sie den Motorschalter kurz, um sicherzustellen, dass der Bohrer nicht wackelt oder vibriert.
- 18- LASSEN SIE DIE SPINDEL VOLLSTÄNDIGE GESCHWINDIGKEIT. erreichen, bevor Sie mit dem Bohren beginnen. Wenn Ihre Bohrmaschine ein ungewohntes Geräusch macht oder übermäßig vibriert, stoppen Sie sofort, schalten Sie die Bohrmaschine AUS und ziehen Sie den Stecker. Starten Sie das Gerät nicht neu, bis das Problem behoben ist.
- 19- FÜHREN SIE KEINE Layoutmontage oder Einrichtungsarbeiten auf dem Tisch durch, während die Bohrmaschine in Betrieb ist.
- 20-VERWENDEN SIE DIE EMPFOHLENE GESCHWINDIGKEIT für jedes Bohrmaschinenzubehör und für unterschiedliche Werkstückmaterialien.
- 21- BEIM BOHREN von Löchern mit großem Durchmesser, klemmen Sie das Werkstück fest an den Tisch. Andernfalls kann der Bohrer das Werkstück bei hohen Geschwindigkeiten erfassen und drehen. VERWENDEN SIE KEINE Flugschneider oder mehrteilige Lochschneider, da sie auseinanderfallen oder im Gebrauch unausgewogen werden können.
- 22- STELLEN SIE SICHER, dass die Spindel vollständig angehalten hat, bevor Sie das Werkstück berühren.
- 23- UM VERLETZUNGEN durch unbeabsichtigtes Starten zu vermeiden, schalten Sie immer den Schalter AUS und ziehen Sie den Stecker der Bohrmaschine heraus, bevor Sie Zubehör oder Anhänge installieren oder



entfernen oder Einstellungen vornehmen.



VERWENDEN SIE DAS RICHTIGE VERLÄNGERUNGSKABEL. Stellen Sie sicher, dass Ihr Verlängerungskabel in gutem Zustand ist. Wenn Sie ein Verlängerungskabel verwenden, stellen Sie sicher, dass es stark genug ist, um den Strom zu tragen, den Ihr Produkt ziehen wird. Ein zu dünnes Kabel verursacht einen Spannungsabfall, was zu einem Leistungsverlust und Überhitzung führt. Stellen Sie sicher, dass Ihr Verlängerungskabel richtig verdrahtet und in gutem Zustand ist. Ersetzen Sie immer ein beschädigtes Verlängerungskabel oder lassen Sie es von einer qualifizierten Person reparieren, bevor Sie es verwenden. Schützen Sie Ihre Verlängerungsk Schützen Sie Ihre Verlängerungskabel vor scharfen Gegenständen, übermäßiger Hitze und feuchten oder nassen Bereichen

WARNUNG!

Zu Ihrer eigenen Sicherheit schalten Sie den Schalter AUS und ziehen Sie den Stecker aus der Steckdose, bevor Sie Ihre Bohrmaschine warten oder schmieren.

Blasen Sie häufig mit einem Luftkompressor oder einem Staubsauger den Staub aus, der sich im Motor ansammelt. Eine Schicht Wachspaste, die auf den Tisch und die Säule aufgetragen wird, hilft, die Oberfläche sauber zu halten und Rost zu vermeiden. Um Stromschlagoder Brandgefahr zu vermeiden, lassen Sie das Netzkabel sofort ersetzen, wenn es abgenutzt oder auf irgendeine Weise geschnitten ist.

SCHMIERUNG

Alle Kugellager der Bohrmaschine sind ab Werk mit Fett gepackt. Sie benötigen keine weitere Schmierung. Senken Sie die Spindel auf die maximale Tiefe und ölen Sie sie einmal alle drei Monate mäßig.




FEHLERSUCHE-TABELLE

Mögliche Ursache(n):	Korrekturmaßnahme	
1. Falsche Riemen Spannung	1. Spannung einstellen	
Bit brennt oder raucht	2. Spindel schmieren	
Übermäßiges Spiel oder Wackeln des Bohrers	3. Riemenscheibenmutter festziehen	
Bohrer klemmt im Werkstück	4. Stellschraube in der Riemenscheibe festziehen	
Falsche Geschwindigkeit	Geschwindigkeit ändern	
Bit häufig zurückziehen, um Späne zu entfernen	2. Bit häufig zurückziehen, um Späne zu entfernen	
3. Bit schärfen oder ersetzen	3. Bit schärfen oder ersetzen	
1. Verbogener Bit	1. Bit ersetzen	
2. Install bit properly	2. Bit richtig einsetzen	
3. Bohrfutter richtig installieren	3. Bohrfutter richtig installieren	
4. Lager ersetzen	4. Lager ersetzen	
Werkstück klemmt Bit oder	Werkstück unterstützen oder klemmen, Vorschubdruck verringern	
2. Spannung einstellen	2. Spannung einstellen	
Werkstück richtig unterstützen oder klemmen	Werkstück richtig unterstützen oder klemmen	
Nicht richtig unterstützt oder geklemmt		
	1. Falsche Riemen Spannung Bit brennt oder raucht Übermäßiges Spiel oder Wackeln des Bohrers Bohrer klemmt im Werkstück 1. Falsche Geschwindigkeit 2. Bit häufig zurückziehen, um Späne zu entfernen 3. Bit schärfen oder ersetzen 1. Verbogener Bit 2. Install bit properly 3. Bohrfutter richtig installieren 4. Lager ersetzen 1. Werkstück klemmt Bit oder 2. Spannung einstellen 1. Werkstück richtig unterstützen oder klemmen 1. Nicht richtig unterstützt oder	



DRILL PRESS 16mm 2604






SPECIFICATIONS

Model	2604	
Voltage	220-240V	
Motor Power	550W	
Chuck Capacity	3~16mm	
Drill Capacity	Steel: 16mm Wood:35mm Plastic: 25mm	
Spindle Travel	80mm	
Class Of Speed	16	
Speed	180~2770RPM	
Spindle Taper	MT2	
Distance from spindle axis to the column	162.5mm	
Distance from spindle end to the surface of table	450mm	
Distance from spindle end to the surface of base	630mm	
Swing	325mm	
Table Size	250x250mm	
Base Size	420X250mm	
Column Diameter	72mm	
Height	980mm	
Net Weight/Gross Weight	39/42Kg	



Accessories	
Spring Washer 10	4
Outside Hex. Bolt M10x25	4
Collar Rack	1
Hexagon Bar Wrench 4	1
Hexagon Bar Wrench 3	1
Handle & Tip	3
Thick Brake Iron	1
Chuck Guard	1
Chuck & Taper Spindle	1
Pulley Cover Tip	1
Cross Recess Pan Hd Screw M5	1
Flat Washer M5	1
Bolt M12x40	4
Bench Vice 4"+D63 4"	1
Flat Washer 12	4
Spring Washer 12	4

PARTS LIST





SPECIFICATIONS



MARNING!

To avoid electrical hazards, fire hazards, or damage to the tool, use proper circuit protection.

Use a separate electrical circuit for your tools. To avoid shock or fire, replace power cord immediately if it is worn, cut or damaged in any way.



WARNING!

To avoid mistakes that could cause serious injury, do not plug the Drill Press in until you have read and understood the following.

- 1- READ and become familiar with the entire Operator's Manual, LEARN the tool's application, limitations and possible hazards.
- 2- KEEP GUARDS IN PLACE and in working order.
- 3- REMOVE ADJUSTING KEYS AND WRENCHES. Form a habit of checking to see that keys and adjusting wrenches are removed from the tool before turning ON.
- 4- KEEP WORK AREA CLEAN. Cluttered areas and benches invite accidents.
- 5- DON'T USE IN DANGEROUS ENVIRONMENT. Don't use power tools in damp or wet locations, or expose them to rain. Keep work area well lighted.
- 6- KEEP CHILDREN AWAY. All visitors should be kept at a safe distance from work area.
- 7- MAKE WORKSHOP CHILDPROOF with padlocks.
- 8- DON'T FORCE THE TOOL. It will do the job better and safer at the rate for which it was designed.
- 9- USE THE RIGHT TOOL. Do not force tool or attachment to do a job for which it was not designed.
- 10- USE PROPER EXTENSION CORD. Make sure your extension cord is in good condition. When using an extension cord, be sure to use one heavy enough to carry the current your product will draw. An undersized cord will result in a drop in line voltage and in loss of power that will cause the tool to overheat.



- 11- WEAR PROPER APPAREL. Do not wear loose clothing, gloves, neckties, rings, bracelets, or other jewelry that may get caught in moving parts. Non-slip footwear is recommended. Wear protective hair covering to contain long hair.
- 12- ALWAYS WEAR EYE PROTECTION. Any Drill Press can throw foreign objects into the eyes that could cause permanent eye damage. ALWAYS wear Safety Goggles (not glasses). Everyday eyeglasses have only impact-resistance lenses. They ARE NOT safety glasses.
- 13- SECURE WORK. Use clamps or a vise to hold work when practical. It's safer than using your hand and it frees both hands to operate tool.
- 14- DISCONNECT TOOLS before servicing; when changing accessories such as blades, bits, cutters, and the like.
- 15- REDUCE THE RISK OF UNINTENTIONAL STARTING. Make sure switch is in OFF position before plugging in.
- 16- USE RECOMMENDED ACCESSORIES. Consult the Operator's Manual for recommended accessories. The use of improper accessories may cause serious injury.
- 17- NEVER STAND ON TOOL. Serious injury could occur if the tool is tipped or if the cutting tool is unintentionally contacted.
- 18- CHECK FOR DAMAGED PARTS. Before further use of the tool, a guard or other part that is damaged should be carefully checked to determine that it will operate properly and perform its intended function check for alignment of moving parts, binding of moving parts, breakage of parts, mounting, and any other conditions that may affect its operation. A guard or other part that is damaged should be properly repaired or replaced.
- 19- NEVER LEAVE TOOL RUNNING UNATTENDED. TURN POWER "OFF". Don't leave tool until it comes to a complete stop. 20- DON'T OVERREACH. Keep proper footing and balance at all times.
- 21- MAINTAIN TOOLS WITH CARE. Keep tools sharp and clean



for best and safest performance. Follow instructions for lubricating and changing accessories.

22- DO NOT use power tools in the presence of flammable liquids or gases.

SAFETY

- 23- DO NOT OPERATE the tool if you are under the influence of any drugs, alcohol or medication that could affect your ability to use the tool properly.
- 24- provide for proper dust removal. Use dust collection systems whenever possible. Dust generated from certain materials can be hazardous to your health.

SPECIFIC SAFETY INSTRUCTIONS



A WARNING!

For your own safety, do not try to use your drill press or plug it in until it is completely assembled and installed according to the instructions, and until you have read and understood this instruction manual.

- 1- THIS DRILL PRESS is intended for use in dry conditions, indoor use only.
- 2- WEAR EYE PROTECTION. USE a face or dust mask along with safety goggles if drilling operation is dusty. USE ear protectors, especially during extended periods of operation.
- 3- DO NOT wear gloves, neckties, or loose clothing.
- 4- DO NOT try to drill material too small to be securely held.
- 5- ALWAYS keep hands out of the path of a drill bit. Avoid awkward hand positions where a sudden slip could cause your hand to move into the drill bit.
- 6- DO NOT install or use any drill bit that exceeds 175mm in length or extends 150mm below the chuck jaws. They can suddenly bend outward or break.
- 7- DO NOT USE wire wheels, router bits, shaper cutters, circle (fly) cutters, or rotary planers on this drill press.
- 8- WHEN cutting a large piece of material, make sure it is fully supported at the table height.



- 9- DO NOT perform any operation freehand. ALWAYS hold the work piece firmly against the table so it will not rock or twist. Use clamps or a vise for unstable work pieces.
- 10- MAKE SURE there are no nails or foreign objects in the part of the work piece to be drilled.
- 11- CLAMP THE WORKPIECE OR BRACE IT against the left side of the column to prevent rotation. If it is too short or the table is tilted, clamp it solidly to the table.
- 12- IF THE WORKPIECE overhangs the table such that it will fall or tip if not held, clamp it to the table or provide auxiliary support.
- 13- SECURE THE WORK. Use clamps or a vise to hold the work when practical. It's safer than using your hand and it frees both hands to operate tool.
- 14- MAKE SURE all clamps and locks are firmly tightened before drilling.
- 15- SECURELY LOCK THE HEAD and table support to the column, and the table to the table support before operating the drill press.
- 16- NEVER turn your drill press ON before clearing the table of all objects (tools, scraps of wood, etc.).
- 17- BEFORE STARTING the operation, jog the motor switch to make sure the frill bit does not wobble or vibrate.
- 18- LET THE SPINDLE REACH FULL SPEED before starting to drill. If your drill press makes an unfamiliar noise or if it vibrates excessively, stop immediately, turn the drill press OFF and unplug. Do not restart the unit until the problem is corrected.
- 19- DO NOT perform layout assembly or set up work on the table while the drill press is in operation.
- 20- USE THE RECOMMENDED SPEED for any drill press accessory and for different work piece material.
- 21- WHEN DRILLING large diameter holes, clamp the work piece firmly to the table. Otherwise, the bit may grab and spin the work piece at high speeds. DO NOT USE fly cutters or multiple-part hold cutters, as they can come apart or become unbalanced in use.
- 22- MAKE SURE the spindle has come to a complete stop before touching



the work piece.

23- TO AVOID INJURY from accidental starting, always turn the switch OFF and unplug the drill press before installing or removing any accessory or attachment or making any adjustment.

A NOTE:

USE PROPER EXTENSION CORD. Make sure your extension cord is in good condition. When using an extension cord,

be sure to use one heavy enough to carry the current your product will draw. An undersized cord will cause a drop in line voltage, resulting in loss of power and cause overheating.

Be sure your extension cord is properly wired and in good condition. Always replace a damaged extension cord or have it repaired by a qualified person before using it. Protect your extension cords from sharp objects, excessive heat and damp or wet areas.

ASSEMBLY

COLUMN SUPPORT TO BASE (FIG 1)

- Position the base on floor or bench.
- -Place the column on the base, aligning the holes in the column support with the holes in the base.
- Locate the four long hex bolts from the loose parts bag.
- Place a bolt in each hole through the column support and the base. Tighten with an adjustable wrench.

INSTALL TABLE (FIG 2)

Slide table assembly over column.

TIGHTEN TABLE BRACKET LOCKING HANDLE TO SECURE TA-**BLE ASSEMBLY. (FIG 3)**

INSTALLING THE HEAD (FIG 4)



- Carefully lift the head above the column and slide it onto the column. Make sure the head slides down over the column as far as possible. Align the head with the base.
- Using the hex wrench, tighten the head lock set screws.

INSTALLING FEED HANDLES (FIG 5)

Locate the three feed handles in the loose parts bag.

- Screw the feed handles into the threaded holes in the hub. Tighten.

INSTALLING THE CHUCK (FIG 6)



A WARNING!

Before any assembly of the chuck and arbor to the drill press head, clean all mating surfaces with a non-petroleum based product; such as alcohol or lacquer thinner. Any oil or grease used in the packing of these parts must be removed; otherwise the chuck may come loose during operation.

- Open the jaws of the chuck by rotating the chuck sleeve clockwise. To prevent damage, make sure the jaws are completely receded into the chuck.
- Push the chuck onto the spindle.


ATTENTION:

Clean the spindle taper with a non-alcohol based cleaner before inserting it into the chuck.

- Using a wood mallet, firmly tap the chuck upward into position on the spindle shaft.



INSTALL KNOB AND SCREW OF UPPER PULLEY COVER. (FIG 7)



ADJUSTMENT

TABLE ADJUSTMENT


A. Tilting adjustment:

Loosen lock bolt then swing table to appropriate position and retighten lock bolt.

B. Swing 360°

Loosen table bracket locking handle then swing table to appropriate position and retighten the locking handle.

C. The scale of down shows work table's degrees rotation





SPEED ADJUSTMENT (FIG 1)

- This drill press has 16 speeds shown in the speed label.

To change the speed, loose the belt tension lock knob, pull the motor mounting plate to the front end then change the belt location.

To tighten the belt, push the motor mounting plate to the rear end and lock the belt tension lock knob.




Fig1

OPEARTIONS

INSTALLING A DRILL BIT (FIG 1)

- With the switch "OFF", open the chuck jaws (1) using the chuck key (2). Turn the chuck key counterclockwise to open the chuck jaws (1).
- Insert the drill bit (3) into the chuck far enough to obtain maximum gripping by the jaws, but not far enough to touch the spiral grooves (flutes) of the drill bit when the jaws are tightened.
- Make sure that the drill is centered in the chuck.
- Turn the chuck key clockwise to tighten the jaws.



A WARNING!

To avoid injury or accident by the chuck key ejecting forcibly from the chuck when the power is turned ON, always recheck and remove the chuck key before turning the power ON.



POSITIONING WORK PIECE (FIG 2)

To prevent the work piece or back-up material from being torn from your hands while drilling, you MUST position it against the LEFT side of the column. Failure to do this could result in personal injury.


USING VISE (FIG 3)

For small work piece that cannot be clamped to the table, use a drill press vise. The vise must be clamped or bolted to the table.



WARNING!

The drill press vise MUST be clamped or bolted to the table to avoid injury from a spinning work piece, or damaged vise or bit parts.



CORRECT DRILLING SPEEDS



WARNING!

Be sure drill press is turned off and is disconnected from power sours before adjusting speeds.

Use the recommended speed for the drill bit and work piece.

The drill bits that can be used is shown in following figure.



Material						
	SOFTWOOD	HARDWOOD	ACRYLIC	BRASS	ALUMINUM	STEEL
		TWIST DRI	ILL BITS			
1/16-3/16" (3-5mm)	3000	3000	2500	3000	3000	3000
1/4-3/8" (6-10mm)	3000	1500	2000	1200	2500	1000
7/16-5/8"(11-16mm)	1500	750	1500	750	1500	600
11/16-1" (11-25mm)	750	500	NR	400	1000	250
		BRAD-POII	NT BITS			
1/8"	1800	1200	1500	NR	NR	NR
1/4``	1800	1000	1500	NR	NR	NR
3/8``	1800	750	1500	NR	NR	NR
1/2``	1800	750	1000	NR	NR	NR
5/8"	1800	500	750	NR	NR	NR
3/4``	1400	250	750	NR	NR	NR
7/8"	1200	250	500	NR	NR	NR
1"	1000	250	200	NR	NR	NR
		FORSTNE	R BITS			
1/4-3/8``	2400	700	250	NR	NR	NR
1/2-5/8``	2400	500	250	NR	NR	NR
3/4-1``	1500	500	250	NR	NR	NR
1 1/8-1 1/4``	1000	250	250	NR	NR	NR
1 3/8-2``	500	250	NR	NR	NR	NR
SPADE BITS						
1/4-1/2``	2000	1500	NR	NR	NR	NR
5/8-1 1/2"	1750	1500	NR	NR	NR	NR
1 1/8-1 1/2``	1500	1000	NR	NR	NR	NR
SPADE BITS WITH SPURS						
3/8-1 NR	2000	1800	500	NR	NR	NR

MAINTENANCE



For our own safety, turn the switch OFF and remove the plug from the



power source outlet before maintaining or lubricating your drill press.

Frequently blow out, using an air compressor or dust vacuum, any dust that accumulates inside the motor. A coat of paste wax applied to the table and column will help to keep the surface clean & help avoid rust. To avoid shock or fire hazard, if the power cord is worn or cut on any way, have it replaced immediately.

LUBRICATION

All of the drill press ball bearings are packed with grease at the factory. They require no further lubrication. Lower spindle to maximum depth and oil moderately once every three months.

TROUBLESHOOTING CHART

Symptom	Possible Cause(s)	Corrective Action
- J	Incorrect belt tension	Adjust tension
	Bit burns or smokes	Lubricate spindle
		2. Lubilicate spiritie
Noisy operation	Excessive drill bit run out or wobble	3. Tighten pulley nut
	Drill bit binds in work piece	4. Tighten set screw in pulley
	1. Incorrect speed	1. Change speed
Bit burns or smokes	2. Retract bit frequently to clear chips	2. Retract bit frequently to clear chips
	3. Sharpen or replace bit	3. Sharpen or replace bit
Excessive drill bit run out or wobble	1. Bent bit	1. Replace bit
	2. Install bit properly	2. Install bit properly
	3. Install chuck properly	3. Install chuck properly
	4. Replace bearings	4. Replace bearings
Drill bit binds in work piece	1. Work piece pinching bit or	1. Support or clamp work piece, decrease feed pressure
	2. Adjust tension	2. Adjust tension
	Support or clamp work piece properly	1. Support or clamp work piece properly
Work piece torn loose from hand	1. No supported or clamped properly	







www.ronixtools.com