




No	Name	Specification
1	Base	
2	Column flange	
3	Motor label	
4	Spring washer	8
5	Outside hex. Bolt	M8×20
6	Outside hex. Bolt	M12×30
7	Spring washer	12
8	Working table	
9	Table support	
10	Angle label	
11	Locking handle	
12	Column	
13	Handle tip	
14	Handle	
15	Gear shaft	
16	Nut	M8
17	A word head screw	M8x12
18	Housing	
19	Hex. Soc set screw	M8×8
20	Wing knob	
21	Motor spring	
22	Motor push rob	
23	Washer	
24	Motor	
25	Outside hex. Bolt	M8×25
26	Damping washer	
27	Cross recess pan hd screw	M5×16
28	Flat washer	5
29	Speed label	
30	Flat washer	6

No	Name	Specification
31	Protector ring	22
32	Cord clamp	
33	Nut	M5
34	Cross recessed pan head screw	M6×10
35	Pulley cover assembly	
36	Roll pin	6×18
37	Protector ring	9
38	Hexagon bar wrench	3
39	Hexagon bar wrench	4
40	Nut	M6
41	Pulley cover tip	
42	Warning label	
43	Hex. Soc set screw	M6×10
44	Motor pulley	
45	Circlip for hole	40
46	Bearing	6203
47	Keyway spindle	
48	Circlip for bearing	22
49	Spindle pulley	
50	Belt	K-630
51	Plug with cable	
52	Nut	M10
53	Spring cover	
54	Spring	
55	Label	
56	Chuck	
57	Cross recess head tapping screw	St2.9x12
58	Switch	Kjd12

No	Name	Specification
59	Calibration label	
60	Cross recessed pan head screw	M4×10
61	Switch box	
62	Cross recessed pan head screw	M4×6
63	Grounded parts	
64	Tooth lock washer	
65	Indicator	
66	Nut	M10
67	Limited bolt	
68	Bearing	6201
69	Washer	
70	Spindle socket	
71	Circlip for bearing	12
72	Chuck guard	
73	Main spindle	
74	Flat washer	6
75	Cross recessed pan head screw	M4×6
76	Outside hex. Bolt	M8×20
77	Bench vice	2.5"
78	Flat washer	6
79	Spring washer	8
80	Nut	M5