



8530

Cordless Screwdriver 6.25MM-3.6V

Number	Name
1	Batch head
2	SD03 activity set
3	steel wire clip
4	active sleeve gasket(thk.)
5	change the output shaft
6	wire clasp
7	output shaft gasket
8	torque cup
9	tuning fork sharpnel
10	thread rings
11	torque spring
12	torque gasket
13	steel ball
14	axle sleeve
15	gearbox case
16	self-locking ring
17	self locking block
18	tooth screw
19	self locking pin
20	oinner gear ring
21	self locked center frame
22	second planet teeth
23	planetarium
24	first planetary teeth
25	gasket
26	motor gear
27	tooth screw
28	SD03 motor cover board
29	electric motor
30	electricity display lampshade
31	battery display PCB
32	rotate lock button
33	lock button spring
34	left and right case
35	left and right case

Number	Name
36	LED lamp
37	self-propelled screw
38	self-propelled screw
39	switch button
40	switch button spring
41	handle case
42	protection panel
43	battery
44	handle case
45	LEDlight button
46	push rod
47	DC socket
48	LED lamp
49	reflector cup
50	LED light convex mirror
51	charger