


CORDLESS TOOLS



Number	Name
1	screw
2	chuck
3	Torsion cup
30	gear
31	screw
38	screw
40	inductance
41	Left and right paddles
46	Battery pack(Small Socket)
46	Battery pack(Large Socket)
47	T-shaped shrapnel
51	Charger(Large Socket)
51	Charger (Small Socket)
52	box
60	gearbox
61	Motor+ gear
62	Speed control button
63	Key and light
64	Left and right Housing
69	battery head shell
70	battery head shell
71	Charger connector L

RS-8013
Cordless drill driver kit

www.ronixtools.com